

LATCH Access Location Warning

2015 Toyota Prius C



NOT CORRECT


1. Slide apart fabric at stitching below LATCH logo



2. Insert LATCH correctly



CORRECT



Over the past several months Pro Consumer Safety has received 13 cases where parents had a 2015 Toyota Prius model C vehicle with a child restraint installed using lower LATCH connected through the wrong location to access anchors. Most of these seats had also been installed by CPST's. Make note when using LATCH in Prius C models. As shown, the opening that is horizontal just below the LATCH logo can be misleading where most of the mistakes were found. The proper location for LATCH entry can be accessed upon sliding apart the fabric stitching that is vertical just below the LATCH logo. CarSeatResource@ProConsumerSafety.com